


SC10

DIAMOND BLADE DATA SHEET

TURBO SEGMENTED RIM

HARD MATERIALS



PRODUCT		DIAMETER		HEIGHT		WIDTH		- BORE		REDUCING RINGS INCLUDED		MACHINES USED
PART NO	CODE NO	ММ	INCH	ММ	INCH	ММ	INCH	ММ	INCH	ММ	INCH	
DA34003	SC10115	115	4 1/2	12	0.472	2.2	0.087	22.23	7/8	N/A	N/A	
DA34004	SC10125	125	5	12	0.472	2.4	0.094	22.23	7/8	N/A	N/A	
DA34005	SC10180	180	7	12	0.472	2.4	0.094	22.23	7/8	N/A	N/A	✐✐♥♥♥₽₽
DA34006	SC10230	230	9	15	0.590	3	0.118	22.23	7/8	N/A	N/A	
DA34007	SC10300	300	_ 12 _	15	0.590	3	0.118	25.4 + P	1 +P	25.4 - 20	1 - 20mm	🍽 🕱 🔊 🚝 🚍 🖉
DA34008	SC10350	350	14	15	0.590	3.2	0.126	25.4 + P	1 + P	25.4 - 20	1 - 20mm	
DA34009	SC10400	410	16	15	0.590	3.4	0.134	25.4 + P	1 + P	25.4 - 20	1 - 20mm	
DA34010	SC10450	450	18	15	0.590	3.6	0.142	25.4 + P	1 + P	N/A	N/A	

WARNING: This product can expose you to "Nickel" which is known to the State of California to cause cancer & birth defects. ADVERTENCIA: Este producto puede exponerlo a un "Niquel" que el Estado de California sabe que causa cáncer y defectos de nacimiento. AVERTISSEMENT: ce produit peut vous exposer à un "Nickel" connu de l'État de Californie pour provoquer le cancer et des malformations congénitales. www.P65Warnings.ca.gov

©2023 Caterpillar. All Rights Reserved. CAT, CATERPILLAR, LET'S DO THE WORK, their respective logos, "Caterpillar Corporate Yellow", the "Power Edge" & Cat "Modern Hex" trade dress as well as corporate & product identity used herein, are trademarks of Caterpillar & may not be used without permission. C6 DIAMOND LLC, a licensee of Caterpillar Inc. SILCA DUST: Workers who are exposed to respirable crystalline silica dust are at increased risk of developing serious silica-related diseases. It is necessary to use saws & other machinery that is equipped with an integrated water delivery system that continuously feeds water to the blade. Operate & maintain all tools in accordance with manufacturer's instructions to minimize dust emissions & always wear the correct ventilator. For more info visit:

www.osha.gov/sites/default/files/publications/OSHA3681.pdf