


LWE10

DIAMOND BLADE DATA SHEET

TURBO SEGMENTED RIM

HARD MATERIALS

600 Pro



PRODUCT		DIAWETER		HEIGHT		WIDTH		- BORE		REDUCING RINGS INCLUDED		MACHINES USED
PART NO	CODE NO	ММ	INCH	ММ	INCH	ММ	INCH	ММ	INCH	ММ	INCH	
DA33007	LWE10115	115	4 1/2	12	0.472	2.2	0.087	22.23	7/8	N/A	N/A	
DA33008	LWE10125	125	5	12	0.472	2.2	0.087	22.23	7/8	N/A	N/A	
DA33009	LWE10180	180	7	12	0.472	2.4	0.094	22.23	7/8	N/A	N/A	
DA33010	LWE10230	230	9	12	0.472	2.5	0.098	22.23	7/8	N/A	N/A	
DA33011	LWE10300	300	_ 12 _	12	0.472	3	0.118	25.4 + P	1 +P	25.4 - 20	1 - 20mm	
DA33012	LWE10350	350	14	12	0.472	3.2	0.126	25.4 + P	1 +P	25.4 - 20	1 - 20mm	🍋 🕱 🛃 🏝 🖻
DA33013	LWE10400	410	- 16 -	12	0.472	3.4	0.134	25.4 + P	1 +P	25.4 - 20	1 - 20mm	
DA33014	LWE10450	450	18	12	0.472	3.6	0.142	25.4 + P	1 +P	N/A	N/A	🍋 🔀 🗾 🗭 🚍 🖉



WARNING: This product can expose you to "Nickel" which is known to the State of California to cause cancer & birth defects. ADVERTENCIA: Este producto puede exponerlo a un "Niquel" que el Estado de California sabe que causa cáncer y defectos de nacimiento. AVERTISSEMENT: ce produit peut vous exposer à un "Nickel" connu de l'État de Californie pour provoquer le cancer et des malformations congénitales. www.P65Warnings.ca.gov

©2023 Caterpillar. All Rights Reserved. CAT, CATERPILLAR, LET'S DO THE WORK, their respective logos, "Caterpillar Corporate Yellow", the "Power Edge" & Cat "Modern Hex" trade dress as well as corporate & product identity used herein, are trademarks of Caterpillar & may not be used without permission. CB DIAMOND LLC, al licenses of Caterpillar Inc. SILICA DUST: Workers who are exposed to respirable crystalline silica dust are at increased risk of developing serious silica-related diseases. It is necessary to use saws & other machinery that is equipped with an integrated water delivery system that continuously feeds water to the blade. Operate & maintain all tools in accordance with manufacturer's instructions to minimize dust emissions & always wear the correct ventilator. For more info visit:

www.osha.gov/sites/default/files/publications/OSHA3681.pdf